

Ditchingham Asset Register 2016

Litter Bins		Location	Emptied By	Freq.	Yearly Cost	Purchase Value	Actions for 2016	PA Report
Small	Tall							
	1	B1332 (Junction Duke of York)	SNDC	W	FoC	100	None	Not Locked. O.K.
1		Broome Heath (Green Lane Entrance)	SNDC	W	FoC	267	Replaced Dec. 2015	New Tall Litter Bin. Not Locked. O.K.
	1	Clarke Rd (Foot path with Loddon Road)	SNDC	W	FoC	100	None - minor broken lid	
	1	Clarke Rd (Junction with Longrigg Road)	SNDC	W	FoC	149	Replaced April 2016	
1		Hollow Hill Rd (Nr Bus Shelter)	SNDC	W	FoC	50	None	Newly installed small post mounted bin. Locked. O.K.
	1	Loddon Road (Dip opposite shop)	SNDC	W	FoC	100	Need cleaning	
	1	Loddon Road (Tunneys Lane Heath entrance)	SNDC	W	FoC	100	None	O.K.
1		Loddon Road (Village Hall bus stop)	SNDC	W	FoC	267	Replaced Dec. 2015	New Tall Litter Bin. Not Locked. (Bin Liner not Fitted). O.K.
1		Pirnhow Street (Cul de Sac)	SNDC	W	FoC	50	None	O.K.
	1	Skate Park	DPC	W	FoC	140	Replaced Jan. 2016	
1		Station Road (Dip entrance gate)	SNDC	W	FoC	50	None	O.K.
1		Thwaite Rd (In Play Area)	DPC	W	FoC	267	Replaced Dec. 2015	MIDDLE – Starting to corrode at bottom.
2		Thwaite Rd (In Play Area)	DPC	W	FoC	100	none	ENTRANCE – Small bin O.K. - New tall bin Not Locked. O.K.
	1	Thwaite Rd (Junction with Hollow Hill Road)	SNDC	W	FoC	100	None - minor broken lid	O.K.
1		Youth Shelter	DPC	W	FoC	50	None	Locked. O.K.
9	7							

Dog Bins		Location	Emptied By	Freq.	Yearly Cost		Action	
1		Falcon Pub foot path (Falcon Meadow)	SNDC	W*2	55	40	None	Just one lid. O.K.
1		Loddon Road (Tunneys Lane Heath entrance)	SNDC	W*2	55	40	None	
2		Loddon Road (Green Lane entrance to Heath)	SNDC	W*2	FoC	84	Replaced Dec. 2015	Just one lid. One O.K. Other has lid that does not fit flush and partley open.
1		Loddon Road/Station Road crossroads (nr shop)	SNDC	W*2	FoC	84	Replaced Dec. 2015	Just one lid. O.K.
1		Pirnhow Street (Cul de Sac)	SNDC	W*2	55	40	None	Just one lid. O.K.
1		Thwaite Rd (Outside of Play Area)	SNDC	W*2	FoC	87	Replaced April 2016	
7		ROUNDABOUT						Just one lid. O.K.
		emptied by (SN, DPC)						
		frequency (W=weekly; W*2=twice weekly; O=Other)						
		cost (annual cost)						

Other	Location	Maintained By				Action	
Bus Shelter	Hollow Hill Road	DPC			2230	Rubbed down/painted 2015	O.K.
Bus Shelter	Loddon Road (village hall)	DPC			3649	New 2015	O.K.
Grit Bin	Green Lane carpark	DPC			50	None	O.K.
Grit Bin	Hollow Hill Road (B1332 junction)	DPC			50	None	Grit Slightly Damp
Grit Bin	Crossroads	DPC			50	None	
Grit Bin	Hollow Hill Road (Opposite Beevors Garden)	DPC			50	None	O.K.
Grit Bin	Pirnhow Street	DPC			50	None	Grit Seems Damp and May not be Easy to Spread
Grit Bin	Thwaite Road (opposite Loke)	DPC			50	None	Very Weathered. Grit also Very Damp & May be Hard to Use.
Lynchgate	Cemetery Entrance	DPC			2507	None	O.K.
Noticeboard	Loddon Road (outside shop)	DPC			200	None	O.K.
Picnic Tables	Play Area x 2	DPC			200	Rubbed down/stained 2015	O.K.
Wood Bench	B1332 (opposite Drapers lane)	DPC			100	Rubbed down/stained 2015	O.K.
Wood Bench	Cemetery ashes area (privately owned)	???			100	None	O.K.
Wood Bench	Cemetery (privately owned)	???			100	None	O.K.
Recycled Bench (Memorial)	Dip (crossroads)	DPC			405	New 2015	O.K.
Recycled Bench (JS)	Loddon Road (opposite shop)	DPC			345	New 2015	O.K.
Picnic benches	The Dip x 2	DPC			490	New 2015	1 Bench. O.K.
Wood/Concr. Bench	Play Area x 2	DPC			100	Rubbed down/stained 2015	3 Benches with Backs. O.K.
Wooden Bench	Play Area	DPC			100	Rubbed down/stained 2015	3 Benches without Backs. O.K.
The Dip							
Skateramps	The Dip	DPC			14500	New 2013	weekly inspected
Teen Shelter/Base	The Dip	DPC			5400	New 2013	weekly inspected
Thwaite Road Play Area							
Play Area	Thwaite Road	DPC			35200	New 2013	weekly inspected
NISA Shop							
Defibrillator & Cabinet	Loddon Road	DPC			1515	New 2016	weekly inspected
Total					£69,706		